

SB: Water Computer

Article : 1881, 1882, 1883, 1884, 1885



**Reason: Due to a wrong component specification on the PCB it can randomly happen that on low flow rates (e.g. when using Micro Drip system) the valve doesn't close anymore .
Concerned products/ batches are:**

1881 with index A
1882 with index A
1883 with index B
1884 with index A
1885 with index B

Actions :

The whole stock was reworked in June 2014 by reprogramming the control units. These units can be identified by :

- silver dot in the battery compartment:



- date sticker on the bottom of the card board:



- additional date sticker on the side of the covering box:



For the production of new control units the index was changed:

- on article 1881, 1882 and 1884 : new production index "**B**"
- on article 1883 and 1885: new production index "**C**"



Note : The new production doesn't have the date stickers !