

<input type="checkbox"/>	Action required:	<input type="checkbox"/>	Sold	<input type="checkbox"/>	Not sold
<input type="checkbox"/>	Only if encountered				
<input checked="" type="checkbox"/>	Information only				

SB, Firmware update m/2019, Automower® 105, Gardena R38Li, R40Li, R45i, R50Li, R70Li, R80Li, McCulloch ROB R600, ROB R800, ROB R1000, Flymo 1200R, 2018-12

Affected models

Model	PNC	Serial Range	
		Start	End
Automower® 105		160100001	184999999
Gardena R38Li		160100001	184999999
Gardena R40Li		160100001	184999999
Gardena R45Li		160100001	184999999
Gardena R50Li		160100001	184999999
Gardena R70Li		160100001	184999999
Gardena R80Li		160100001	184999999
McCulloch ROB R600		160100001	184999999
McCulloch ROB R800		160100001	184999999
McCulloch ROB R1000		160100001	184999999
McCulloch Flymo 1200R		160100001	194599999

Affected market(s)

All.

Description

New firmware has been released, firmware package 5825856-08A. The firmware package contains the following changes:

- Extended foot detection (added to comply with future iterations of the robotic standard regulation, EN 50636-2-107):
 - Added extended functionality to identify if the mower runs over a foot or similar objects when reversing
 - When an object is identified the product will stop its blade motor and try to move away from the identified object
 - Having moved away from the object the mower will start cutting again after 25 seconds.
- Several minor firmware improvements (not described in detail in this SB).

<input type="checkbox"/>	Action required:	<input type="checkbox"/>	Sold	<input type="checkbox"/>	Not sold
<input type="checkbox"/>	Only if encountered				
<input checked="" type="checkbox"/>	Information only				

Dealers are recommended to update the software:

- As a normal part of PDI prior to sales of a new product
- In case of a customer complaint on any of the issues described above
- At latest at next service.

Revision History

Rev.	Date	Order id.	Description
A	2018-12	SB-3673	Created