

SB: **Sprinklers ZoomMaxx, OS140 and OS90**

Articles : 8127, 8128, 8220, 8221, 8222, 8361



Reason: Leakage of sprinkler head, part no. 8220-00.610.00

On sprinklers with sprinkler head index **702x – 705x** (February – May 2017) we found a leakage on the grey side cover due to a faulty ultrasonic welding. The failure rate of these sprinklers is 0,5 -1,0%.

Actions: The stock in Ulm was sorted out. All sprinkler heads with index 706x and newer are ok and all deliveries from Ulm since May 2017 are ok too !

position of the index:



position of leakage:

