

SB: **Water Computer EasyControl**

Article : 1881, 1882,



Reason: Software defect:

We found out that on some control units a defect software version is installed. The concerned control units have the **index 611B**:



The defect can be recognized by the customers on the display. Either there is no display after inserting the battery or the markings for the date functions are missing.

Actions: Exchange of the control unit 1881-00.510.00