

<input type="checkbox"/>	Action required:	<input type="checkbox"/>	Sold	<input type="checkbox"/>	Not sold
<input type="checkbox"/>	Only if encountered				
<input checked="" type="checkbox"/>	Information only				

SB, Firmware update m/2019, Gardena Sileno/Sileno+ (R100Li/R130Li/R160Li), smart Sileno/smart Sileno+ (R100LiC/R130LiC/R160LiC), 2018-12

Affected models

Model	PNC	Serial Range	
		Start	End
Gardena R100Li	All	154200001	184999999
Gardena R130Li	All	154200001	184999999
Gardena R160Li	All	154200001	184999999
Gardena R100LiC	All	154200001	184999999
Gardena R130LiC	All	154200001	184999999
Gardena R160LiC	All	154200001	184999999

Affected market(s)

All.

Description

New firmware has been released, firmware package 5825861-11C. The firmware package contains the following changes:

- Extended foot detection (added to comply with future iterations of the robotic standard regulation, EN 50636-2-107):
 - Added extended functionality to identify if the mower runs over a foot or similar objects when reversing
 - When an object is identified the product will stop its blade motor and try to move away from the identified object
 - Having moved away from the object the mower will start cutting again after 25 seconds.
- Spot cutting
 - Functionality to trigger spot cutting added in the HMI.
- Several minor firmware improvements (not described in detail in this SB).

Dealers are recommended to update the software:

- As a normal part of PDI prior to sales of a new product
- In case of a customer complaint on any of the issues described above
- At latest at next service.

<input type="checkbox"/>	Action required:	<input type="checkbox"/>	Sold	<input type="checkbox"/>	Not sold
<input type="checkbox"/>	Only if encountered				
<input checked="" type="checkbox"/>	Information only				

Revision History

Rev.	Date	Order id.	Description
A	2018-12	SB-3679	Created