

SB: **New mower blades**

Article : 4016, 4017



Reason: The 37cm and 42 cm blades were modified to improve the cutting performance, the durability and to reduce the wear. The new blades can be identified by the missing notch and a crooked cutting edge.

old blade



new blade



Without notch

Crooked cutting
edge

The article no. was not changed but the blades got a new packaging:

new package



old package



Remarks:

- The stock in Ulm was adjusted, only new versions are available.
- In cases of repairs and replacements the new blades must be used.