

Service Bulletin B1201007A-07

| Action required | |
|------------------|---|
| Information only | Χ |

SB, Firmware update m/2020, Gardena Sileno, Sileno+, 2020-01

Affected models

| Model | PNC | Serial | Serial Range | |
|-----------------|-----|-----------|--------------|--|
| | | Start | End | |
| Gardena Sileno | All | 160100001 | 195199999 | |
| Gardena Sileno+ | All | 160100001 | 195199999 | |

Affected markets

All.

Description

New firmware has been released: firmware package 5825861-14B. The firmware package contains the following changes:

- Changed temperature limits for battery charging.
 - o Required to support new regulations and to improve the lifetime of the battery.
 - o See detailed information under "Additional information".
- Several minor bugfixes and improvements.

Revision History

| | | • | |
|------|---------|-----------|-------------|
| Rev. | Date | Order id. | Description |
| Α | 2020-01 | SB-5174 | Created |

English Page 1 of 1