

## Service Bulletin B4210019A-06

Action required		
Information only	Χ	

# SB, Software Bundle 5995762-03A will be released soon, Gardena SILENO minimo, 2021-12

#### Affected models

Model	Serial Range
SILENO mínimo 200	All
SILENO mínimo 250	All
SILENO mínimo 300	All
SILENO mínimo 380	All
SILENO mínimo 400	All
SILENO mínimo 450	All
SILENO mínimo 500	All
SILENO mínimo 600	All

#### Affected markets

All.

#### **Description**

A new version of mower software will be released for the affected models (see above).

The software will be released together with new release version 1.2 of customer upgrade tool (planned in 12/2021).

This includes the following changes:

- Charging current supervision
  - Check if charging current is as expected. If this is not the case, the mower will dock again (up to 8 times). If still not as expected, the mower will show error 30 (charging system error).
- Start-on-start
  - Mower starts mowing when pressing "start button" twice, even if battery is not fully charged.
- Support for ZoneProtect.
- Support for new security code handling at los PIN code (256byte).
- Bug fixes.

It is strongly recommended to update the mowers at next service!

English Page 1 of 2



# Service Bulletin B4210019A-06

Action required	
Information only	Χ

# Warranty reporting information

Nothing in this SB can be subject to warranty claims. Warranty claims will not be accepted.

### Revision History

Rev.	Date	Order id.	Description
Α	2021-12	00015769	Created

English Page 2 of 2