

Service Bulletin B4210020A-06

Action required	
Information only	

SB, Software Bundle 5825861-17A has been released, Gardena (smart) SILENO (+), 2021-12

Affected models

Model	Serial Range
SILENO (R100Li)	2016 and newer
smart SILENO (R100LiC)	2016 and newer
SILENO (R100Li)	2016 and newer
smart SILENO (R100LiC)	2016 and newer
SILENO+ (R130Li)	2016 and newer
smart SILENO + (R130LiC)	2016 and newer
SILENO+ (R160Li)	2016 and newer
smart SILENO+ (R160LiC)	2016 and newer
SILENO (R200Li)	2016 and newer
smart SILENO+ (R200LiC)	2016 and newer

Description

A new version of mower software has been released for the affected models (see above).

This includes the following changes:

- Charging current supervision
 - Check if charging current is as expected. If this is not the case, the mower will dock again (up to 8 times). If still not as expected, the mower will show error 30 (charging system error).
- All models have Sensor Control.
- Support for ZoneProtect.
- Support for new security code handling at los PIN code (256byte).
- Bug fixes.

It is strongly recommended to update the mowers at next service!

Warranty reporting information

Nothing in this SB can be subject to warranty claims. Warranty claims will not be accepted.

Revision History

Rev.	Date	Order id.	Description
Α	2021-12	00015770	Created

English Page 1 of 1